

QU-192A, Pitampura, Delhi-110088 Ph.: 0091-11-32921827

To Whom so Ever It May Concern

This is to certify that the structure parts of the building for senior secondary school i.e. Queen Mary's School on plot No. 4 A, Northend, Model Town, Delhi – 110 009 have been designed in accordance as stipulated under clause 18 of building bye laws 1983.

This is also certify that the structure design including safety norms from natural hazard on soil condition has been duly incorporated in the design of the structure part of the building and theses provisions have been adhered to during the construction.

This is further certify that the building is safe for occupation.

(Arun Singhat) A 84/8

Årun Singhal CA 84/8218

Manager Principal Queen Mary's School Norward Model Town, DELHI-110009

नगर निगम



MUNICIPAL CORPORATION OF DELHI

OFFICE OF THE ASSISTANT ENGINEER-II M.S.O. BUILDING, 16, RAJPUR ROAD, DELHI.

No. A.E. -II M-III CLZ 2005-09 50 Dated 14-8-2003

Building Fitness Certificate

This is to certified that the structural part of the senior secondary schools building on Plot No. 4-A, North of Model Town, Delhi ig pucca, sound & safe for running a school.

Oneen Mary's School, Worthand Plot No 4-2, Model Town-III) Delhi -110007.

Micalopal Corporation of Dalba

Civil Line Zone

Manager Principal Queen Mary's School Northend Model Town, LELHI-110009

APPENDIX'H' FORM-1 DELHI DEVELOPMENT ATHORITY

(BUIDING SECTION)

C-I BLOCK, 1ST FLOOR. VIKAS SADAN, · NEW DELHI

File No.: - F13 (188)2002/Bldg./

Date

Τó

Sr. Sec. School, Plot no.A4, Model Town, New Delhi Section D.D. For Helen Jerwood Managinal D. For Helen Jerwood Memorial Education Society

COMPLETION CERTIFICATE

With reference to your notice of completion dated 20.03.2008, I hereby certify that the building as per description below certified plans of Sr. Sec. School, Plot No.-A4, Model Town, New Delhi For Helen Jerwood Memorial Education Society, whose plans were sanctioned vide No.F13(188) 2002/ Bldg./99 dated 24.10.2005 has been inspected with reference to Building Bye-Laws in respect of the structural safety, fire safety, hygienic and sanitation conditions inside and in the surroundings and is declared fit for occupation.

The structural stability of the building is based on the certificate given jointly by the Owner/Architect/Structural Engineer along with one set of structural Drawings, incorporating therein the provisions of structural Safety as per specified in the relevant prevailing IS Codes/ Standards/ Guidelines stated in the Government of India Notification bearing No. SO-248(E) dated 21.3.2001. For the fire safety the same has been based on the clearance given by the Chief Fire Officer, Government of NCT of Delhi. The DDA shall not have any responsibility for any loss caused to the building from any natural hazard calamity. This is subject to adherence and compliance of conditions required in Annexure "A" enclosed.

Completion Certificate is issued for Ground floor to 3rd Floor to Sr. Sec. School, Plot No.-A4, Model Town, New Delhi for Helen Jerwood Memorial Education Society along with enclosed drawings.

> Dy.Director (B) L&I FOR VICE CHAIRMEN

Copy to:-

1. CFO, Delhi Fire Service, Headquarters New Delhi.

- 2. The Registrar, Cooperative Societies, Delhi-Administration, Parliament Street, New Delhi-
- 3. Chief Engineer, DDA, East Zone, New Delhi.
- 4. Dy. Director (IL), DDA.
- 5. Record File.

ANNEXURE "A"

File No. F13 (188)2002/Bldg.

1. Copy of lease deed executed on 05.06.2006

2. Structural Stability Certificate issued by Owner/ Architect/ Structural Engineer & Supervisor dated 29.02.2008

3. Time of Extension is up to 31.03.2008 & CC is applied on 20.03. 2008.

4. NOC from CFO vide No.F6/DFS/MS/School/2012/4743 dated 21.12.2012

5. NOC from Civil Aviation vide letter No.AAI/NOC/2005/129/52-54 dated 06.10.2005.

Note:

It is the responsibility of the Society to adhere to and comply with conditions of CFO, Lease Deed and any other conditions, clearance obtained by the Society vide documents mentioned above.

Any loss of life and property due to non-functioning of fire protection arrangement and other installation shall be the responsibility of the management of the Society.

In case of any material change or deviation is made in the completion plan, as it exist today, this certificate will be rendered invalid.

Encl: As above.

(K.M.Saxéna)

Dy.Director (B) L&I' FOR VICE CHAIRMAN

DDA



NORTH DELHI MUNICIPAL CORPORATION HEALTH DEPARTMENT CIVIL LINE ZONE 16, Rajpur Road Delhi-54

Nothing...DHO/CLZ/2013

Date 23/3/2013

Health Certificate

Name of the School

Queen Mary's School, North End

Location of the School

Plot No. 4A, Model Town-III Delhi

Date of Inspection

20/03/2013

Total Number of Students

2882

No. of Class Rooms

95

No. of Urinals/Toilets

13 (Female)+03(Male)=16

No of staff members

155

- 1. All rooms are well ventilated white washed, and well lighted.
- 2. First Aid Box is also arranged in proper manner.
- 3. General sanitation and hygienic and properly maintained in this school up to mark for health point of view.
- 4. Number of class rooms as per strength of the student sufficient.

In view the above submissions, this Health certificate is being issued in favour of this school by the undersigned, after being fully satisfied and having no objection from Health Point of View.

Dy. Health Officer

Civil Lines Zone
North Delhi Municipal Corporation